OLGA BRENER INTERMEDIATE SCHOOL BIKE/WALK AUDIT RESULTS



High Traffic Volume at Dismissal

Crossing Guard

No Sidewalk

Area Used by Most Parents to **Pick-Up Students**

Bus Loading Area

Source: Aerial photography Shawano County, 2011. ECWRPC provided the school location and bike and walk audit results.

Audit Conducted 10.19.2011 - P.M.

200 400 Scale in Feet





