MARION JUNIOR HIGH SCHOOL BIKE/WALK AUDIT RESULTS

Excessive Traffic Volume & Speed

Bike Racks

No Sidewalk

Bus Loading Area

Area Used by Most Parents Picking-Up Students

Trails Connecting To / Through Park

Source: Aerial photography Waupaca County, 2010. ECWRPC provided the school location and bike and walk audit results.		
0	200	400

Scale in Feet

Audit Conducted 05.15.2012 - P.M.

This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

