JEFFERSON ELEMENTARY SCHOOL BIKE/WALK AUDIT RESULTS

Areas Used by Most Vehicles Dropping-Off Students

Bus Loading Area

Bike Racks

= = = No Sidewalk

= = = Multi-Use Trail

Bike/Peds & Vehicles Dropping-Off Observed During Audit	
Bikes	0
Peds	2
Vehicles	57

Source: Aerial photography and base data Winnebago County, 2010. ECWRPC provided the school location and bike and walk audit results.

0 100 20 Scale in Feet



Audit Conducted 11.21.2013 - A.M.

This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Map Prepared December, 2013 by:



