## **Taft Elementary School**

## Bicycle & Walk Audit


Crossing Guard

Pedestrian Sign School Zone Sign

**Legend** 

Bike Rack

Parent Pick Up & Drop Off **Bus Loading Zone** General Parking Staff Parking No Parking



Source: Base data provided by Winnebago County 2015. SRTS data provided by ECWRPC 2019.

PREPARED OCTOBER 2019 BY:



