NEW LONDON MIDDLE SCHOOL BIKE/WALK AUDIT RESULTS

S

High Traffic Volume at Dismissal

Bus Loading Area

Source: Aerial photography Waupaca County, 2010. ECWRPC provided the school location and bike and walk audit results. 200

Scale in Feet

400

٠. الله ال

Audit Conducted 11.01.2011 - P.M.

No Sidewalk

- **Bike Racks**

Area Used by Most Parents **Picking-Up Students**

This data was created for use by the East Central Wisconsin Regional Planning
Commission Geographic Information System. Any other use/application of this
information is the responsibility of the user and such use/application is at their
own risk. East Central Wisconsin Regional Planning Commission disclaims all
liability regarding fitness of the information for any use other than for East
Central Wisconsin Regional Planning Commission business.

Map Prepared By EAST CENTRAL WISCONSIN REGIONAL PLANNING COMMISSION-JANUARY 2012

