READFIELD ELEMENTARY SCHOOL BIKE/WALK AUDIT RESULTS

Bus Loading Area

Area Used by Parents Picking-Up Students

Source: Aerial photography Waupaca County, 2010. ECWRPC provided the school location and bike and walk audit results.

0 200 40 Scale in Feet



Audit Conducted 11.03.2011 - P.M.

This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Map Prepared By EAST CENTRAL WISCONSIN REGIONAL PLANNING COMMISSION-JANUARY 2012

