LAKESHORE ELEMENTARY SCHOOL BIKE/WALK AUDIT RESULTS

Excessive Traffic Speed

- - No Sidewalk

Bus Loading Area



Area Used by Most Parents Picking-Up Students

Multi-Use Trail

Source: Aerial photography City of Fond du Lac, 2010. ECWRPC provided the school location and bike and walk audit results.

Scale in Feet



Audit Conducted 02.10.2009

This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Map Prepared By EAST CENTRAL WISCONSIN REGIONAL PLANNING COMMISSION-NOVEMBER 2011

