


LINCOLN ELEMENTARY SCHOOL BIKE/WALK AUDIT RESULTS

Source: Base data provided by Outagamie County, 2010.
ECWRPC provided the school location and
bike and walk audit results.

Audit Conducted
10.16.2013 - A.M.

-  Excessive Traffic Volume & Speed
-  Heavy Traffic at School Arrival
-  Crossing Guard
-  Student Safety Patrol
-  Areas Used by Most Vehicles Dropping-Off Students
-  Bus Loading Area
-  Bike Racks
-  Valley Transit -- Route 3



This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Map Prepared March, 2014 by:

