


# GEGAN ELEMENTARY SCHOOL BIKE/WALK AUDIT RESULTS

Source: Aerial photography and base data Winnebago County, 2010. ECWRPC provided the school location and bike and walk audit results.

Audit Conducted  
12.05.2013 - A.M.



This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Map Prepared December, 2013 by:



High Traffic Volume  
During Peak Times



Bike Racks



Areas Used by Most Vehicles  
Dropping-Off Students



Crossing Guard



Bus Loading Area



No Sidewalk

Bike/Peds & Vehicles Dropping-Off Observed During Audit	
Bikes	0
Peds	21
Vehicles	106

