

MAPLEWOOD MIDDLE SCHOOL BIKE/WALK AUDIT RESULTS

Source: Aerial photography and base data Winnebago County, 2010. ECWRPC provided the school location and bike and walk audit results.

Audit Conducted
11.20.2013 - A.M.



Very High Traffic Volume
During Peak Times -- Some
High Speeds Observed



Bike Racks



Valley Transit Route



Crossing Guard


No Sidewalk

Valley Transit Bus Stop

Areas Used by Most Vehicles
Dropping-Off Students

Bus Loading Area - Busses Only

Bike/Peds & Vehicles Dropping-Off Observed During Audit	
Bikes	3
Peds	36
Vehicles	187



This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Map Prepared December, 2013 by:

