

COOLIDGE ELEMENTARY SCHOOL BIKE/WALK AUDIT RESULTS

Source: Aerial photography and base data Winnebago County, 2010. ECWRPC provided the school location and bike and walk audit results.

Audit Conducted
05.26.2011 - P.M.

0 200 400
Scale in Feet



This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Prepared By
EAST CENTRAL WISCONSIN
REGIONAL PLANNING COMMISSION-SEPTEMBER 2011



-  A Few Parents Double Parked and Picked-Up Students in Street
-  Heavy Traffic at Dismissal
-  Crossing Guard
-  No Sidewalk
-  Areas Used by Most Parents Picking-Up Students
-  Bus Loading Area - Busses Only
-  "Cut Through" Sidewalk Connection

