









PERRY TIPLER MS - GREEN MEADOW ES BIKE/WALK AUDIT RESULTS

-  Excessive Traffic Volume & Speed
-  High Traffic Volume During Arrival/Dismissal
-  Student Safety Patrol for Franklin ES
-  Bike Racks
-  Bus Loading Area
-  Area Used by Most Parents Picking-Up Students
-  Oshkosh Transit -- Route 7

Source: Aerial photography Winnebago County, 2010. ECWRPC provided the school location and bike and walk audit results.

Audit Conducted
12.05.2012 - A.M.



This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Map Prepared By
EAST CENTRAL WISCONSIN
REGIONAL PLANNING COMMISSION-DECEMBER 2012

