


BARLOW PARK ELEMENTARY SCHOOL BIKE/WALK AUDIT RESULTS

Source: Aerial photography from ESRI online. Base data Fond du Lac County, 2010. ECWRPC provided the school location and bike and walk audit results.

Audit Conducted
11.24.2012 - A.M.

-  Excessive Traffic Volume & Speed
-  Bus Loading Area
-  No Sidewalk
-  Area Used by Most Parents Picking-Up Students
-  'Cut Through' Sidewalk Connection



This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Prepared By
EAST CENTRAL WISCONSIN
REGIONAL PLANNING COMMISSION-JANUARY 2012

