










HILLCREST PRIMARY SCHOOL BIKE/WALK AUDIT RESULTS

Source: Aerial photography Shawano County, 2011.
ECWRPC provided the school location and
bike and walk audit results.

Audit Conducted
10.09.2012 - P.M.

-  Excessive Traffic Speed
-  High Traffic Volume at Dismissal
-  Crossing Guard
-  Bike Racks
-  Bus Loading Area
-  Area Used by Most Parents Picking-Up Students
-  No Parking Area
-  No Sidewalk



This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Prepared By
EAST CENTRAL WISCONSIN
REGIONAL PLANNING COMMISSION-OCTOBER 2012

