

# SHAWANO MIDDLE SCHOOL BIKE/WALK AUDIT RESULTS

Source: Aerial photography Shawano County, 2011.  
ECWRPC provided the school location and  
bike and walk audit results.

Audit Conducted  
10.19.2011 - P.M.



High Traffic Volume at Dismissal



Area Used by Most Parents to  
Pick-Up Students




Crossing Guard



Bus Loading Area



No Sidewalk



This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Prepared By  
EAST CENTRAL WISCONSIN  
REGIONAL PLANNING COMMISSION-OCTOBER 2011

