


# WAUPACA MS & EARLY LEARNING CENTER BIKE/WALK AUDIT RESULTS

-  High Traffic Volume & Speeds
-  Heavy Traffic During Drop-Off/Pick-Up Times
-  Crossing Guard
-  Bus Loading Area
-  Parent Pick-Up/Drop-Off Areas
-  Existing Sidewalk
-  No Sidewalk

Source: Aerial photography Waupaca County, 2010. ECWRPC provided the school location and with the help of Waupaca Early Learning Center students and staff the bike and walk audit results.

Audit Conducted  
05.21.2012 - A.M.



This data was created for use by the East Central Wisconsin Regional Planning Commission Geographic Information System. Any other use/application of this information is the responsibility of the user and such use/application is at their own risk. East Central Wisconsin Regional Planning Commission disclaims all liability regarding fitness of the information for any use other than for East Central Wisconsin Regional Planning Commission business.

Prepared By  
EAST CENTRAL WISCONSIN  
REGIONAL PLANNING COMMISSION-JUNE 2012

